



# CD 50

## DESICCANT DRYING TABLET

Free water and vapor is a common impurity found in natural gas. Operating problems caused by condensing water vapor can include: gas line freeze ups, line plugging because of hydrate formation, compromised capacity from water collecting in the lines, and corrosion to the pipeline. Most pipeline companies require some level of gas quality. **CD 50** is an inexpensive way to reduce moisture content of natural gas to prevent these problems.

**CD 50** can be used in systems to reduce water content. The tablet allows for good contact between the gas stream and the medium to gain maximum drying effectiveness.



---

HARDER, MORE  
DENSE TABLETS  
RESIST CAKING,  
CHANNELING,  
BLOOMING AND  
DUSTING

---

MINIMIZES RE-  
CRYSTALLIZATION  
IN SUMP WITH GAS  
TEMPERATURES  
ABOVE 29°C (85°F)

---

CONVENIENT  
PACKAGING.

---

SMALL  
FOOTPRINT

**INTERRACHEM, LLC**

PO Box 727  
Newburgh, IN 47628

[www.interrachem.com](http://www.interrachem.com)